

## Hole #11 Project

Hole #11 has some issues that need to be addressed.

Some of the cart paths on this hole have deteriorated and need repair. These need to be repaired and roughly 4 pallets of sod need to be placed on either side of the cart path.

There are 8-10 trees that need to be removed from the right hand side near the cross bunkers. Most of these trees are damaged at the roots. Roughly 3 pallets of sod need to be placed in the area near these trees.



Bare area in the right side fairway of #11 near the trees



Cart path on #11 that needs repair.



Tree on #11 with damage at the roots.



Another tree on #11 with damage

### Projected Cost

Tree removal	\$2400
Stump grinding	\$900
Cart path repair	\$3000
Bermudagrass sod prep & lay	\$1800
<b>Total</b>	<b>\$8100</b>